AIRPROX REPORT No 2023208

Date: 06 Sep 2023 Time: 1420Z Position: 5249N 00334W Location: 6NM S Bala

PART A: SUMMARY OF INFORMATION REPORTED TO UKAB

Recorded	Aircraft 1	Aircraft 2	Landderfel
Aircraft	ASH26	Light aircraft	Diagram based on radar and EC device data
Operator	Civ Gld	Unknown	Llanyci C Rhos-y-gwaliau
Airspace	London FIR	London FIR	
Class	G	G	Dinam
Rules	VFR	VFR	ASH26 2126
Service	None	NK	Pont Cowin Pydew
Provider	N/A	NK	
Altitude/FL	~4020ft	4100ft	CPA 1420:18
Transponder	Not fitted	A, C	1936 ~100ft V/<0.1NM H
Reported			~4260ft 295 Melangel Pen
Colours	White	NK	~4120ft ly-nant A041 2006
Lighting		NK	~4200ft ~4020ft A041
Conditions	VMC	NK	-2054 Allforgan
Visibility	>10km	NK	1420:02 Cello A042
Altitude/FL	4200ft	NK	•2247 G1419:46 1827
Altimeter	QNH	NK	VBURY 1419:30 1617.
Heading	135°	NK	ARS
Speed	55kt	NK	3.150 1959 1867
ACAS/TAS	PowerFLARM	NK	Lanymawddwyy
Alert	None	NK	Unknown a
	Separation	on at CPA	-1560 -1787 - Dyfnant
Reported	200ft V/0NM H	NK	Earact
Recorded	~100ft V/	<0.1NM H	

THE ASH26 PILOT reports that they had self-launched from [their departure point] and were exploring mountain wave and thermals. A weak wave was forming immediately downwind of the ridges. They had climbed to 4500ft, just east of Lake Bala, and were aiming southeast towards clouds that were marking possible lift adjacent to the Vyrnwy valley. In level cruise, they were suddenly aware of an aircraft headon and closing quickly. They immediately pushed the stick and ducked under its path. It passed immediately over their head, no more than 200ft above (their dip was 200ft). There was no alert from their [EC device]. As far as they could tell, [the other pilot] didn't see them.

The pilot assessed the risk of collision as 'High'.

THE PILOT of the other aircraft involved could not be traced.

Factual Background

The weather at Shawbury was recorded as follows:

METAR EGOS 061420Z 24002KT CAVOK 28/19 Q1019 NOSIG RMK BLU BLU

Analysis and Investigation

UKAB Secretariat

An analysis of the NATS radar replay was undertaken. The ASH26 was not observed on radar. Two aircraft were observed on radar to have been in the vicinity at the time of the Airprox, one of which was quickly discounted from having been involved (see Figure 1). The other aircraft could not be positively identified but is believed to have been involved. Despite best efforts, and having ascertained a probable identity, the pilot of that aircraft could not be definitively established.

The pilot of the ASH26 kindly supplied GPS track data for their flight. It was by combining the separate sources that the diagram was constructed and the separation at CPA determined. The untraced aircraft was observed on radar to have been flown at Flight Levels and an appropriate conversion factor was used to determine its altitude.



Figure 1 – CPA at 1420:18

The ASH26 pilot and the pilot of the untraced aircraft shared an equal responsibility for collision avoidance and not to operate in such proximity to other aircraft as to create a collision hazard.¹ If the incident geometry is considered as head-on or nearly so then both pilots were required to turn to the right.²

Comments

AOPA

Unfortunately, even in today's world of technology with integrated resources, not all aircraft can be identified, which makes the investigation process more difficult. The use of the Low Level Common frequency, or SafetyCom, can assist in everyone's situational awareness.

BGA

This incident once again highlights the difficulty of seeing an aircraft approaching head-on on a reciprocal course.

Summary

An Airprox was reported when an ASH26 and an untraced aircraft flew into proximity 6NM south of Bala at 1420Z on Wednesday 6th September 2023. The pilot of the ASH26 had been operating under VFR in VMC. It could not be determined if the pilot of the untraced aircraft had been in receipt of an ATS.

PART B: SUMMARY OF THE BOARD'S DISCUSSIONS

Information available consisted of a report from the ASH26 pilot, GPS track data and radar photographs/video recordings. Relevant contributory factors mentioned during the Board's discussions

¹ (UK) SERA.3205 Proximity.

² (UK) SERA.3210 Right-of-way (c)(1) Approaching head-on.

are highlighted within the text in bold, with the numbers referring to the Contributory Factors table displayed in Part C.

The Board appreciated the effort that had been made to identify the pilot of the untraced aircraft but was disappointed that, ultimately, it had not been possible. Notwithstanding, members began their discussion by considering the actions of the pilot of the ASH26. A member with particular knowledge of gliding operations explained that it would have been very difficult for the pilot of the ASH26 to have sighted an aircraft that had been heading directly towards them due to the small frontal aspect that it had presented and lack of relative motion. The matter of electronic conspicuity was pondered and, although it was not known whether the untraced aircraft had carried any EC equipment other than a transponder transmitting Mode A and C data, members agreed that the EC device fitted to the ASH26 would have been expected to have detected its presence. Given the proximity of the aircraft, members were surprised that the pilot of the ASH26 reported that they had not received an alert (**CF2**). Consequently, it was agreed that the pilot of the ASH26 had not had situational awareness of the presence of the untraced aircraft (**CF1**). Nevertheless, members agreed that upon visual acquisition, albeit late (**CF3**), the pilot of the ASH26 had reacted quickly to take avoiding action.

Concluding their discussion, members agreed that the pilot of the ASH26 had taken decisive avoiding action but safety during the encounter had not been assured. Members were in agreement that there had been a risk of collision (**CF4**) and that it had been the emergency action taken by the pilot of the ASH26 that had increased separation between the aircraft at the last minute. As such, the Board assigned Risk Category B to this event.

PART C: ASSESSMENT OF CONTRIBUTORY FACTORS AND RISK

	2023208										
CF	Factor	Description	ECCAIRS Amplification	UKAB Amplification							
	Flight Elements										
	Situational Awareness of the Conflicting Aircraft and Action										
1	Contextual	 Situational Awareness and Sensory Events 	Events involving a flight crew's awareness and perception of situations	Pilot had no, late, inaccurate or only generic, Situational Awareness							
	Electronic Warning System Operation and Compliance										
2	Human Factors	Response to Warning System	An event involving the incorrect response of flight crew following the operation of an aircraft warning system	CWS misinterpreted, not optimally actioned or CWS alert expected but none reported							
	See and Avoid										
3	Human Factors • Identification/ Recognition		Events involving flight crew not fully identifying or recognising the reality of a situation	Late sighting by one or both pilots							
	Outcome Events										
4	Contextual	Near Airborne Collision with Aircraft	An event involving a near collision by an aircraft with an aircraft, balloon, dirigible or other piloted air vehicles								

Contributory Factors:

Degree of Risk:

Safety Barrier Assessment³

Β.

In assessing the effectiveness of the safety barriers associated with this incident, the Board concluded that the key factors had been that:

³ The UK Airprox Board scheme for assessing the Availability, Functionality and Effectiveness of safety barriers can be found on the <u>UKAB Website</u>.

Flight Elements:

Situational Awareness of the Conflicting Aircraft and Action were assessed as ineffective because the pilot of the ASH26 had not had situational awareness of the presence of the untraced aircraft.

Electronic Warning System Operation and Compliance were assessed as **ineffective** because the EC device fitted to the ASH26 would have been expected to have detected the presence of the untraced aircraft, but no alert was reported.

See and Avoid were assessed as **partially effective** because the pilot of the ASH26 had visually acquired the untraced aircraft late.

	Airprox Barrier Assessment: 202320	8 Outside	Contr	olled Airspace	9			
	Barrier	Provision	Application	% 5	%	Effectiveness Barrier Weighting 10%	15%	20%
Ground Element	Regulations, Processes, Procedures and Compliance							
	Manning & Equipment		\bigcirc					
	Situational Awareness of the Confliction & Action							
	Electronic Warning System Operation and Compliance	e 🔵						
Flight Element	Regulations, Processes, Procedures and Compliance	0						
	Tactical Planning and Execution							
	Situational Awareness of the Conflicting Aircraft & Acti	ion 😢						
	Electronic Warning System Operation and Compliance	e 🔇						
	See & Avoid	0						
	Key: Full Partial None Not F Provision Image: Constraint of the second sec	Present/Not Ass	essabl	le <u>Not Used</u>				